Owner Name and Address: Farmers Union Trading Co 1st Ave S & Pratten St PO Box 509 Columbus MT 59019 Phone: (406) 322-5214

Columbus

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 10 Currently in Use	1033	10/1/1992 13 / No	Gasoline 5,500	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
2 / 11 Currently in Use	1034	10/1/1992 13 / No	Diesel 2,500	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJ&L ● ●EFGHIJ&L</pre>	Yes Yes Yes Yes
3 / 12 Currently in Use	1035	10/1/1992 13 / No	Diesel 2,500	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABC) EFGH (JK) (D) (D) (EFGH (JK)	Yes Yes Yes Yes
13 / 13 Currently In Use	4731	7/1/1998 08 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJKL ● ●EFGHIJKL</pre>	Yes Yes Yes Yes
14 / 14 Currently In Use	1037	7/1/1998 08 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 1 of 13

Owner Name and Address: Krueger Oil Co PO Box 805 Columbus MT 59019 Phone: (406) 322-4421

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4805082	Krueger Oil Co	800 Clough Ave S	Columbus	59019	(406) 322-4421

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
6 / S6 Currently in Use	1919	6/1/1994 12 / Ye	Gasoline 1,000	Other None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCDEFGHIJ®L B DEF•HIJØL	Yes Yes Yes Yes
7 / S7 Currently in Use	1920	6/1/1994 12 / Ye	Diesel 1,000	Other None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	(ABCDEFGH) J. (L) (B) (B) (F) (H) (J) (L)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed	

Report Generation Date: 7/3/2006 Page 2 of 13

Owner Name and Address: Gits Inc 740 Pike Ave PO Box 336 Columbus MT 59019 Phone: (406) 322-4111

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4807859	Gits Conoco	740 E Pike Ave	Columbus	59019	(406) 322-4111

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3209	5/8/1979 27 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Impressed Current	Pressurized	<pre></pre>	Yes Yes Yes Yes
2 / 02 Currently in Use	3210	5/8/1979 27 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Impressed Current	Pressurized	(ABC) (EFGH) () (L)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 13

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4808691	Town Pump Inc Columbus UST	602 E 8th Ave N	Columbus	59019	(406) 322-4833

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	2646	5/1/1984 22 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC@EFGHIJKL</pre>	Yes Yes Yes Yes
6 / 06 Currently in Use	2647	9/1/1984 21 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKU • • EFGHIJKU	Yes Yes Yes Yes
7 / 07 Currently in Use	2648	12/29/1988 17 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABC ● EFGH1JKL ● •EFGH1JKL	Yes Yes Yes Yes
8 / 08 Currently in Use	2649	11/1/1988 17 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
9 / 09 Currently in Use	2650	11/1/1988 17 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
10 / 10 Currently in Use	2651	11/1/1988 17 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
11 / 11 Currently In Use	4064	6/25/1999 07 / No	Diesel 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B OEFOHIJKL	Yes Yes Yes Yes
12 / 12 Currently In Use	4065	6/25/1999 07 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	B	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 4 of 13

13 / 13 Currently In Use	4066 6/25/1999 07 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	B	Yes Yes Yes Yes
14 / 14 Currently In Use	4933 12/30/2004 01 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 5 of 13

Owner Name and Address: Bill & Katy Martin PO Box 130 Fishtail MT 59028 Phone: (406) 328-4260

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4803599	MDOT ROW Fishtail General Store FHW	35 W Main St	Fishtail	59028	(406) 328-4260

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	1086	5/1/1993 13 / No	Diesel 1,000	Polyethylene Tank Jacket None	Flexible Plastic Double-Walled	Safe Suction	ABCOEFGHIJKL B DEFOHIOKL	Yes Yes Yes Yes
3 / 03 Currently in Use	1087 5	5/1/1993 13 / No	Gasoline 1,002	Polyethylene Tank Jacket None	Flexible Plastic Double-Walled	Safe Suction	(ABCOEFGHIJKL B (DEFOHIOKL)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed	

Report Generation Date: 7/3/2006 Page 6 of 13

Owner Name and Address: Bill and Judy Henderson 1997 Nye Road Fishtail MT 59028 Phone: (406) 328-6262

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4809647	Nye Trading Post	MT Highway 419	Fishtail	59028	(406) 328-6262

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	1296	10/1/1993 12 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	ABC • E F G H 1 J K L B D E F G H 1 • K L	Yes Yes Yes Yes
4 / 04 Currently in Use	1297	10/1/1993 12 / No	Diesel 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(A B C • E F G H) J (K L) (B D E F G H) • (K L)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 7 of 13

Owner Name and Address: Francis H Abbott Jr 633 Fiddler Creek Road Fishtail MT 59028 Phone: (406) 328-4059

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613917	Fishtail Basin Ranch	633 Fiddler Creek Road	Fishtail	59028	(406) 328-6957

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1	4400 3/1/1999	Heating Oil	Polyethylene Tank Jacket	Flexible Plastic	U.S. Suction	ABCDEF.H.I.J.K.L.	Yes
Currently In Use	07 / No	4,000	Double-Walled	Double-Walled		B. DEF.H.I.J.K.L.	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 8 of 13

Owner Name and Address: O & M Properties LLC PO Box 660 Absarokee MT 59001 Phone: (406) 328-6248

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5613932	Olies Corner Store Fishtail	2993 MT Highway 78	Fishtail	59028	(406) 328-6248	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	4038	5/1/1999 07 / No	Diesel 2,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABCOEFGHIJKL</pre>	Yes Yes Yes Yes
2 / 02 Currently In Use	4039	5/1/1999 07 / No	Diesel 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABCOEFGHUJ&L</pre>	Yes Yes Yes Yes
3 / 03 Currently In Use	4040	5/1/1999 07 / No	Diesel 6,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABCOEFGHUJKL O EFGHUJKL</pre>	Yes Yes Yes Yes
4 / 04 Currently In Use	4041	5/1/1999 07 / No	Gasoline 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	<pre></pre>	Yes Yes Yes Yes
5 / 05 Currently In Use	4042	5/1/1999 07 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 9 of 13

Owner Name and Address: Marge Keating PO Box 128 Park City MT 59063 Phone: (406) 633-2730

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4806610	Kwik Stop Inc	1 N Clark St	Park City	59063	(406) 633-2730

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently In Use	1507	5/5/1997 09 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABC ● E F G H 1 J K L B D E F G H 1 ● K L	Yes Yes Yes Yes
4 / 04 Currently In Use	1508	5/5/1997 09 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABCOEFGHIJKL B DEFGHIOKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed	

Report Generation Date: 7/3/2006 Page 10 of 13

Owner Name and Address: Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address		Location City	Zip	Location Phone	
4808910	Kum and Go Store 829	Exit 426 & Interstate 90	Ī	Park City	59063	(406) 633-2359	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
8 / 08 Currently in Use	568 5,	/1/1992 14 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes
9 / 09 Currently in Use	569 5,	/1/1992 14 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
10 / 10 Currently in Use	570 5	/1/1992 14 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	B • E F G H 1 J K L	Yes Yes Yes Yes
11 / 11 Currently in Use	571 5	/1/1992 14 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKU B OEFGHIJKU	Yes Yes Yes Yes
12 / 12 Currently in Use	572 5	/1/1992 14 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes
13 / 13 Currently in Use	573 5	/1/1992 14 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes
14 / 14 Currently In Use	574 8	/1/1998 07 / No	Diesel 15,000	STI-P3 None	Galvanized Steel Impressed Current	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 11 of 13

15 / 15	575 8/1/1998 Diesel	STI-P3	Galvanized Steel F	Pressurized	(ABCOEFGHIJKL	Yes
Currently In Use	07 / No 15,000	None	Impressed Current		• • EFGHIJKL	Yes Yes Yes
16 / 16 Currently In Use	576 8/1/1998 Diesel 07 / No 15,000	STI-P3 None	Galvanized Steel Finpressed Current	Pressurized	(ABCOEFGHIJKL) (BEFGHIJKL)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 12 of 13

Owner Name and Address: Kenneth V & Julie Pratton 4 Division St PO Box 392 Reed Point MT 59069 Phone: (406) 326-2319

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4801521	Reedpoint Sinclair	4 Division St	Reed Point	59069	(406) 326-2319

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3303	12/10/1986 19 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<pre>A • C • E F G H J K L • • E F G H J K L</pre>	Yes Yes Yes Yes
2 / 02 Currently in Use	3304	12/10/1986 19 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<pre></pre>	Yes Yes Yes Yes
3 / 03 Currently in Use	3305	12/10/1986 19 / No	Diesel 4,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	A • C • E F G H 1 J K L • • E F G H 1 J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 13 of 13